

Technical requirement:

1. Each cutting tube connect by "V" shape spring strip;
2. Connect each tube by elastic rope accordingly;
3. Oxidize the surface of aluminum tube;
4. Packing finish after dismantle;
5. Tighten the screw to secure the structure stable;
6. the product size must be same as drawing after assembled.

chang 2017.3.10




CANDEX DISPLAYS (CHINA) CO. LTD

ASSEMBLY DRAWING

11						
10						
9						
8						
7						
6						
5						
4	0308101	RING SCREW	M6*50mm	4		
3	01073	POLE	L:1103mm	8	30*1.2 OXIDE TUBE	
2	01073	CROSS TUBE 2	L:1025mm	8	30*1.2 OXIDE TUBE	
1	01073	CROSS TUBE 1	L:1269mm	8	30*1.2 OXIDE TUBE	
NO.	P/N	NAME	SPEC	QTY	MATERIAL	NOTE

REV. MARK	REV. NO.	SIGNATURE & DATE
DESIGN	CB 2017-03-10	TECHNICS
CHECK		STC
AUDITOR		APPROVE



UNIT	SCALE
mm	1:25

SHEET 1 OF 9

CDX-E005-DI

TRACED DRAW

DRAW AND CHECK

OLD DRAW NO.

DRAW NO.

REV A2